

April 9, 2012

To: Our Valued Customers

Attention: Procurement Manager

Subject: **PLC12022A – Product EOL/Obsolescence Notification**

In the previous notice, PLC12022, the CP82C84A and CP82C84AZ were mistakenly included in the list of Intersil devices being put into the end of life cycle. The CP82C84A and CP82C84AZ devices have been removed from the notice and are active for procurement. Intersil will continue to produce these devices for the foreseeable future. For any questions regarding the availability of these devices, please contact your local Intersil Sales person.

You are hereby provided notice that the Intersil products included on the attached parts list are being discontinued. As a valued customer, and one that has previously purchased one or more of such parts, Intersil Corporation is pleased to offer you a final life-of-type procurement for these parts. Recognizing that you will need some time to analyze your requirements, Intersil will accept orders for these products through the LTB/WTHD date provided in the attached list. All shipments under such orders shall be scheduled no later than the SHIP/OBSOLETE date provided. Intersil will attempt to honor all such purchase orders and scheduled delivery dates, but reserves the right to not accept new orders or to cancel existing orders if such orders cannot be filled through reasonable commercial effort.

Please review the lists and make adjustments as necessary in your database.

The information contained herein is intended for the recipients use only. Please limit the distribution of this material to those individuals within your immediate organization having a need to act upon the information. In the event that additional distribution outside of your internal organization is necessary, please notify Intersil and the distribution list for discontinued products will be updated as appropriate.

If you are considering a redesign, and require assistance, please contact your local Sales or Rep office, or the Intersil Corporate Line, 1-888-468-3774, for our Central Applications Department.

*Jon Kline
GCCN Customer Relations Dept.
Intersil Corporation*

Exact Intersil Part # No other variation is being impacted.	Notice PLC12022 Issue Date	LTB / WTHD DATE	SHIP/ OBSOLETE DATE	Replacement/ Similar/ Re-Design
HI3-0518-5Z	3-Apr-2012	28-Sep-2012	3-Apr-2013	NONE
ICL3222CPZ	3-Apr-2012	28-Sep-2012	3-Apr-2013	NONE
ISL6219ACAZ	3-Apr-2012	28-Sep-2012	3-Apr-2013	NONE
ISL6219ACAZ-T	3-Apr-2012	28-Sep-2012	3-Apr-2013	NONE
ISL6334ACCRZ	3-Apr-2012	28-Sep-2012	3-Apr-2013	NONE
ISL6334ACCRZ-T	3-Apr-2012	28-Sep-2012	3-Apr-2013	NONE
ISL9219AIRZ	3-Apr-2012	28-Sep-2012	3-Apr-2013	ISL9219IRZ
ISL9219AIRZR5332	3-Apr-2012	28-Sep-2012	3-Apr-2013	NONE
ISL9219AIRZ-T	3-Apr-2012	28-Sep-2012	3-Apr-2013	ISL9219IRZ-T
MERCURY-104N	3-Apr-2012	28-Sep-2012	3-Apr-2013	MERCURY-204N
RKP9000	3-Apr-2012	28-Sep-2012	3-Apr-2013	NONE
RKP9000R5471	3-Apr-2012	28-Sep-2012	3-Apr-2013	NONE
RKP9000-TK	3-Apr-2012	28-Sep-2012	3-Apr-2013	NONE
RKP9000-TKR5471	3-Apr-2012	28-Sep-2012	3-Apr-2013	NONE
VENUS3-107N	3-Apr-2012	28-Sep-2012	3-Apr-2013	ISL55162CNEZ